

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated:

It is certified that the existing building CHRIST CHURCH VIDYAPITH (name of the building or premises) at BISM Complex, Kodukulanji P.O.

..... (address) is having block(s)/Floor(s) as per details below:


Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	GF-867.96m ² FF-1574.66m ²					

The building is owned/occupied by CHRIST CHURCH VIDYAPITH (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of ALA Panchayat (Name of Department/ Govt.) on (date of inspection) in the presence of Prof. Samuel K. Samuel, Director & Bursar (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from for a period of 1 years in accordance with rule and subject to compliance of the specific conditions as appended.

- The structures are sound under normal wind
- and weather conditions.
-
-

Issued on 27/5/25 at Kodukulanji by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.



Signature with Seal : [Signature]

Name : [Signature]

Designation ASSISTANT ENGINEER

Name & Address of Department/ Office: LID & EW SECTION
ALA CHURCH PANCHAYATH